D.A. ZULUAGA CONSTRUCTION, INC.

RECEIVED

JAN 2 1 1998

KING COUNTY INTERNATIONAL AIRPORT

January 19, 1998

96-316-027

King County International Airport PO Box 80245 Seattle, Washington 98108

Attn: Mr. Jeffrey Winter, P.E.

Re: Contract No. C63179C - Oil Separator Work

"Drainage System Cleaning"

Dear Jeff:

Per addendum #1, we should assume that the sediments from the cleaning process will contain petroleum products. In addition to a petroleum test, Rabanco is also requiring a TCLP test for the presence of metals. We will forward the costs associated with this extra expense for your review.

I would also ask that you wash the credit request for crushed rock at Separator #16 with the need to oversize manholes #19, #23, #26 and #27 to 54" diameter.

Please contact me with any questions you might have.

Sincerely,

Mike Skagen

Project Manager

July 100 miles of the property of